


F101 "Stealth" Survival Light

User Manual

F101 is a multi-function survival light which can be mounted on helmet. It is mainly used to identify and locate in law enforcement, military operations and training such as MFF, maritime, patrol or search and rescue operations.



INSTRUCTIONS FOR USE:

1. Install / replace battery

Unscrew the screw of the battery cover, open the battery cover, put the battery in (Attention + /- direction), then close the battery cover and tighten the screw back.

2. Switch mode

When the switch in the "convex" position: The F101 is visible light mode after turning on.

When the switch in the "flat" position: The F101 is IR light mode after turning on.

3. Function switch

- When the switch in the "0" position: The F101 in the off state.
- When the switch in the "1" position:
 - In the visible light mode, the F101 enters the green light constant light identification mode.
 - In IR light source mode, F101 enters us standard (60fps) IR stroboscopic mode.
- When the switch in "2" position:
 - In the visible light mode, the survival light enters the green light constant light identification + white light stroboscopic positioning mode.
 - In IR light source mode, survival lamp enters into NATO standard (30fps) IR stroboscopic mode.

WARNING:

1. Please confirm that the "+" and "-" poles of the battery are installed correctly otherwise the product will not work.
2. The maximum working temperature of the product is 60 ° C, avoiding high temperature environment or fire.
3. Please do not look directly at the light source for a long time to avoid eyes injury.
4. Please do not disassemble or modify the product structure at will, or you will not get the warranty service.
5. Please put it where children can not get it.

WARRANTY SERVICE

OPSMEN all products are warranted for quality. The DOA / defective products can be exchanged for replacement through a local distributor/dealer within 15 days of purchase. If pass over 15 days, all defective / malfunctioning OPSMEN products will be repaired free of charge for a period 1year from the date of purchase. If you need to replace important parts, only need pay the freight.

This warranty does not apply to the following conditions

1. Man-made destruction, disassembly, modification of this product.
2. Incorrect operation causes damage to the product (such as installing a reverse battery, etc.).
3. Use inferior battery, battery leakage causes product damage.

About more the latest information on OPSMEN products and services, please contact your national OPSMEN distributor or email to cs@opsmen.com

OPERATION

Output	Green	White	IR
Functions	Constant	Flash	US(60fpm)
			NATO(30fpm)
Runtime	200h	56h	10h

SPECIFICATION:

Weight (without battery): 60g

Size : 85 x 55 x 34 mm

Waterproof: IPX8

Working temperature: - 20 °C ~ 60 °C

Battery: 1 x CR123A



RoHS
MADE IN CHINA

OPSMEN Tech Co., Ltd.

: Add: Room 601, Building A, No.94 Liwan
Road, Liwan District, Guangzhou,
Guangdong Province, China 510170

OPSMEN